

ASRF/M Turbo4

**Super Radius Mill Four Corners
for High Performance Milling**

D35 mm ~ D100 mm

- Modular & Bore Types
- 4 Cutting Edges **Turbo4**
- Insert Geometry
- CAM Radius: **R4.5**



www.moldino.eu

🇬🇧 ASRF TURBO4

The ASRF with economical 4-corner specification for increased processing efficiency ensures stable high-performance machining with constant load – even for deep cutting operations.

🇩🇪 ASRF TURBO4

Der ASRF mit wirtschaftlicher 4-seitiger Schneidplattengeometrie für höchste Effizienz ermöglicht Hochleistungs-Bearbeitungen mit konstantem Vorschub – auch bei großen Schnitttiefen.

🇮🇹 ASRF TURBO4

Il ASRF, nella conveniente versione a 4 angoli per una migliore efficienza di lavoro, assicura una lavorazione stabile di elevate prestazioni con un carico costante, anche per operazioni di taglio profondo.

🇪🇸 ASRF TURBO4

El ASRF con especificación económica de 4 esquinas para aumento de eficiencia de procesamiento, asegura un estable funcionamiento de máquina con constante carga – aún para operaciones de corte profundas.

🇫🇷 ASRF TURBO4


Le ASRF, avec ses plaquettes spécifiques dotées de quatre arrêtes de coupe, permet des usinages hautes performances grâce à sa stabilité et la constance de la charge requise. Ceci même lors d'usinages avec de forts porte-à-faux.

🇵🇹 ASRF TURBO4

A ASRF Turbo 4 com a económica especificação de 4 arestas para uma maior eficiência de processamento, assegura um funcionamento estável da máquina com carga constante – até em operações de corte mais profundas.



Recommended Selection of MOLDINO's Roughing Series

	ASR Pico D 16–66 mm	ASRF D 35–100 mm	ASF D 63–315 mm
			
Application Field	HFM High Feed Machining	HPC High Performance Cutting	HVC High Volume Cutting
Machine-spindle	ISO40/HSK63 ASR Pico	ASRF	ISO50/HSK100 ASF
f_z mm	0.5 ~ 1.5	0.5 ~ 2.5	0.5 ~ 3.5
V_f mm/min	2,000 ~ 20,000	1,000 ~ 10,000	500 ~ 5,000
a_p mm	0.35 ~ 0.75 (max. 1)	0.5 ~ 1.5 (max. 2)	0.75 ~ 2 (max. 3)
CAM R	R2	R4.5	R5
Way to achieve Q (cm ³)			
V_c	Less	More	Less
f_z	Less	More	Less
a_p	Less	More	Less
	Less	More	Less
	More	Less	More



ASRFM | Turbo4 Modular

Q max	Jet	▽	▽▽	HRC	No. of Teeth
High Efficient	Air Hole	Roughing	Semi-Finishing	60	3 ~ 4





Diameter Holder only [mm]	CAM Radius:	Fastening Torque [Nm]
0/-0.2 mm	4.5 mm	2.9 Nm

Modular Type												
ID Code	Item Code	Flutes	D	D ₁	H	d ₁	M	d ₂	A	B	Inserts	
FH114	ASRFM-4035R-3-M16	3	35	17	40	17	16	29	6	23	SD..1205ZDTN-R15	
FH115	ASRFM-4042R-4-M16	4	42	24								

ASRF | Turbo4

Q max	Jet	▽	▽▽	HRC	No. of Teeth
High Efficient	Air Hole	Roughing	Semi-Finishing	60	4 ~ 8



Diameter Holder only [mm]	CAM Radius:	Fastening Torque [Nm]
0/-0.2 mm	4.5 mm	2.9 Nm

Bore Type												
ID Code	Item Code	Flutes	D	D ₁	H	d ₁	M	d ₂	A	B	Inserts	
FH108	ASRF-4042RM-4-16	4	42	24	40	16	8*	35	3	18	SD..1205ZDTN-R15	
FH217	ASRF-4050RM-4-22		50	32				47				
FH273	ASRF-4050RM-5-22					22	10	40	16.5	20		
FH109	ASRF-4052RM-5-22	5	52	34	50			45	15.5			
FH113	ASRF-4052RM-5-27		63	45				60	13	22		
FH219	ASRF-4063RM-5-27		66	48		27	12					
FH110	ASRF-4066RM-5-27		80	62				27				
FH111	ASRF-4080RM-6-27	6	80	62	70			70	25	25.5		
FH112	ASRF-4100RM-8-32	8	100	82		32	16					


* Special Screw

Cutting Conditions | Schnittwerte | Condizioni di taglio | Condiciones de Corte | Conditions de coupe | Valores de corte:

D 35 (Z3) – D 42 (Z4) modular & bore type Page 5 D 50 (Z4) – D 100 (Z8) bore type Page 6–7


INSERTS ASRF/M | Turbo4/Turbo4 Modular

Type A



Standard type

Type B






Low-resistance breaker type

<div>Soft<div>Target Hardness of Workpiece</div>Hard</div>											Size (mm)			Chip-breaker	Type
Inserts	Grade														
Item Code	GX2140	JX1060	JM4060	JS4060	JX1045	JS4045	JX1020	JP4020	JX1005	JP4005	R	T	W		
SDNW-1205ZDTN-R15	WF239	WF175	WF366	WF332	WF174	WF375	WF173	WF331	WF172	WF330	15	5.56	12.7	no	A
SDMT-1205ZDTN-R15	WF238	WF180	WF335	WF334	WF179	WF374	WF178	WF333	WF177					yes	B

GX2140	CVD · For heavy roughing of mild steels Recommended for dry cutting
JX1060	PVD · For carbon steels < 35 HRC
JM4060	PVD · For stainless steels & carbon steels < 35 HRC
JS4060	PVD · For carbon steels < 35 HRC
JX1045	PVD · General grade for 30–40 HRC Recommended for dry cutting

JS4045	PVD · For general steels 30–40 HRC
JX1020	PVD · For pre-hardened steels 40–55 HRC
JP4020	PVD · For pre-hardened steels 40–55 HRC
JX1005	PVD · PVD Coating
JP4005	PVD · For hardened steels > 50 HRC



Cutter Body / Parts		Clamp Screw	Item-Code	Wrench	Item-Code
		ID-Code		ID-Code	
		ET048	262-142	ET049	105-T15
		Special screw			
		ID-Code	Item-Code		
		ET050	K06-676		

ASRF / M | Recommended Cutting Conditions

ISO40 / HSK63

Work piece material	Recommend grade & Target hardness (HRC)			Emulsion	Mist	Air	Parameter	D 35 (Z3) Modular				D 42 (Z4) modular & bore type			
	30	40	50					Q max	3D - 5D	5D - 7D	> 7D	Q max	3D - 5D	5D - 7D	> 7D
I II Carbon-Steel Alloy-Steel <30HRC	GX2140						• V_c m/min	200	160	130	100	200	160	130	100
							• n min ⁻¹	1,820	1,460	1,180	910	1,520	1,210	990	760
	JS4060					• •	• f_z mm/t	2	2	1.5	1.5	2	2	1.5	1.5
	JX1060					• •	• V_f mm/min	10,910	8,730	5,320	4,090	12,130	9,700	5,910	4,550
	JS4045						• a_p mm	1.5	1.5	1.0	0.75	1.5	1.5	1.0	0.75
	JX1045						• a_e mm	24.5	24.5	24.5	24.5	29.5	29.5	29.5	29.5
III Alloy-Steel Tool-Steel 30~40HRC	GX2140						• V_c m/min	160	128	104	80	160	128	104	80
							• n min ⁻¹	1,460	1,160	950	730	1,210	970	790	610
	JS4060					• •	• f_z mm/t	2	2	1.5	1.5	2	2	1.5	1.5
	JX1060					• •	• V_f mm/min	8,730	6,980	4,260	3,270	9,700	7,760	4,730	3,640
	JS4045						• a_p mm	1.2	1.2	0.8	0.6	1.2	1.2	0.8	0.6
	JX1045						• a_e mm	24.5	24.5	24.5	24.5	29.5	29.5	29.5	29.5
IV Pre-Hardened Steel Tool-Steel 40~50HRC							• Q cm ³ /min	401	321	127	75	537	429	170	101
							• V_c m/min	120	96	78	60	120	96	78	60
							• n min ⁻¹	1,090	870	710	550	910	730	590	450
	JS4045						• f_z mm/t	1.5	1.5	1.2	1.2	1.5	1.5	1.2	1.2
	JX1045						• V_f mm/min	4,910	3,930	2,550	1,960	5,460	4,370	2,840	2,180
							• a_p mm	1	1	0.7	0.5	1	1	0.7	0.5
V Hardened steel Tool-Steel 50~55HRC							• a_e mm	24.5	24.5	24.5	24.5	29.5	29.5	29.5	29.5
							• Q cm ³ /min	120	96	41	24	161	129	54	32
							• V_c m/min	100	80	65	50	100	80	65	50
							• n min ⁻¹	910	730	590	450	760	610	490	380
							• f_z mm/t	1	1	0.7	0.7	1	1	0.7	0.7
							• V_f mm/min	2,730	2,180	1,240	950	3,030	2,430	1,380	1,060
V Hardened steel Tool-Steel > 55HRC							• a_p mm	0.7	0.7	0.5	0.35	0.7	0.7	0.5	0.35
							• a_e mm	24.5	24.5	24.5	24.5	29.5	29.5	29.5	29.5
							• Q cm ³ /min	47	37	14	8	63	50	19	11
							• V_c m/min	80	64	52	40	80	64	52	40
							• n min ⁻¹	730	580	470	360	610	490	390	300
							• f_z mm/t	0.8	0.8	0.5	0.5	0.8	0.8	0.5	0.5
VIII Cast-Iron GG EN-JL10** EN-GJL-***							• V_f mm/min	1,750	1,400	710	550	1,940	1,550	790	610
							• a_p mm	0.5	0.5	0.3	0.25	0.5	0.5	0.3	0.25
							• a_e mm	24.5	24.5	24.5	24.5	29.5	29.5	29.5	29.5
							• Q cm ³ /min	21	17	6	3	29	23	8	4
							• V_c m/min	200	160	130	100	200	160	130	100
							• n min ⁻¹	1,820	1,460	1,180	910	1,520	1,210	990	760
VIII Cast-Iron GGG EN-JS10** EN-GJS-***							• f_z mm/t	2	2	1.5	1.5	2	2	1.5	1.5
							• V_f mm/min	10,910	8,730	5,320	4,090	12,130	9,700	5,910	4,550
							• a_p mm	1.5	1.5	1.0	0.75	1.5	1.5	1.0	0.75
							• a_e mm	24.5	24.5	24.5	24.5	29.5	29.5	29.5	29.5
							• Q cm ³ /min	401	321	127	75	537	429	170	101
							• V_c m/min	160	128	104	80	160	128	104	80
VI Stainless Steels High alloy Steels							• n min ⁻¹	1,460	1,160	950	730	1,210	970	790	610
							• f_z mm/t	1.5	1.5	1.2	1.2	1.5	1.5	1.2	1.2
							• V_f mm/min	6,550	5,240	3,410	2,620	7,280	5,820	3,780	2,910
							• a_p mm	1.5	1.5	1.0	0.75	1.5	1.5	1.0	0.75
							• a_e mm	24.5	24.5	24.5	24.5	29.5	29.5	29.5	29.5
							• Q cm ³ /min	241	193	81	48	322	258	109	64

NOTES

1. Make sure to use air blow to remove the thick and heavy chips produced when using this tool. Blockage of chips can result in tool breakage. The recommended method is „Spindle centre through air blast“. (Pay much attention to chip removal when using vertical machining centres).
2. To maintain safe cutting conditions ensure effective chip removal before running machine unmanned.
3. To avoid tool breakage, it is important to replace the inserts when wear occurs.

BEMERKUNGEN

1. Wenn möglich, während der Bearbeitung Luft-Kühlung einsetzen, um die dicken & schweren Späne gut abzuleiten bzw. aus der Folge-Bearbeitung fernzuhalten. Verbleibende Späne könnten die WSP beschädigen. Wir empfehlen, wenn möglich, die Luft durch das Werkzeug/den Halter zu fördern. Bitte aufpassen bei vertikalen Bearbeitungen (von Zeit zu Zeit ist die Maschine zu stoppen, um Späne zu entsorgen).
2. Um den Prozess zu sichern, bitte vor der Bearbeitung die Späne-Entsorgung bedenken (eventuell horizontal spannen).
3. Um Wendeplatten-Brüche zu vermeiden, ist es wichtig, die Platten bei auftretendem Verschleiß zu wechseln/zu drehen.

ASRF / M | Recommended Cutting Conditions

ISO50 / HSK100

Work piece material	Recommend grade & Target hardness (HRC)			Emulsion	Mist	Air	Parameter	D 50 (Z4) bore type				D 50 / D 52 (Z5) bore type			
	30	40	50					Q max	3D - 5D	5D - 7D	> 7D	Q max	3D - 5D	5D - 7D	> 7D
I II Carbon-Steel Alloy-Steel <30HRC	GX2140						• V_e m/min	200	160	130	100	200	160	130	100
							• n min ⁻¹	1,270	1,020	830	640	1,220	980	800	610
	JS4060					• •	• f_z mm/t	2	2	1.5	1.5	2	2	1.5	1.5
	JX1060					• •	• V_f mm/min	10,190	8,150	4,970	3,820	12,240	9,790	5,970	4,590
	JS4045						• a_p mm	1.5	1.2	1.1	0.9	1.5	1.5	1.0	0.75
	JX1045						• a_e mm	35	35	35	35	37	37	37	37
III Alloy-Steel Tool-Steel 30~40HRC	GX2140						• V_e m/min	160	128	104	80	160	128	104	80
							• n min ⁻¹	1,020	810	660	510	980	780	640	490
	JS4060					• •	• f_z mm/t	2	2	1.5	1.5	2	2	1.5	1.5
	JX1060					• •	• V_f mm/min	8,150	6,520	3,970	3,060	9,790	7,840	4,770	3,670
	JS4045						• a_p mm	1.2	1.0	0.8	0.7	1.2	1.2	0.8	0.6
	JX1045						• a_e mm	35	35	35	35	37	37	37	37
IV Pre-Hardened Steel Tool-Steel 40~50HRC							• Q cm ³ /min	342	219	117	77	435	348	138	81
							• V_e m/min	120	96	78	60	120	96	78	60
							• n min ⁻¹	760	610	500	380	730	590	480	370
	JS4045						• f_z mm/t	1.5	1.5	1.2	1.2	1.5	1.5	1.2	1.2
	JX1045						• V_f mm/min	4,580	3,670	2,380	1,830	5,510	4,410	2,860	2,200
							• a_p mm	1	0.8	0.7	0.6	1	1	0.7	0.5
V Hardened steel Tool-Steel 50~55HRC							• a_e mm	35	35	35	35	37	37	37	37
							• Q cm ³ /min	160	103	58	38	204	163	69	41
							• V_e m/min	100	80	65	50	100	80	65	50
							• n min ⁻¹	640	510	410	320	610	490	400	310
							• f_z mm/t	1	1	0.7	0.7	1	1	0.7	0.7
							• V_f mm/min	2,550	2,040	1,160	890	3,060	2,450	1,390	1,070
V Hardened steel Tool-Steel > 55HRC							• a_p mm	0.7	0.6	0.5	0.4	0.7	0.7	0.5	0.35
							• a_e mm	35	35	35	35	37	37	37	37
							• Q cm ³ /min	62	40	20	13	79	63	23	14
							• V_e m/min	80	64	52	40	80	64	52	40
							• n min ⁻¹	510	410	330	250	490	390	320	240
							• f_z mm/t	0.8	0.8	0.5	0.5	0.8	0.8	0.5	0.5
VIII Cast-Iron GG EN-JL10** EN-GJL-***							• V_f mm/min	1,630	1,300	660	510	1,960	1,570	800	610
							• a_p mm	0.5	0.4	0.35	0.3	0.5	0.5	0.3	0.25
							• a_e mm	35	35	35	35	37	37	37	37
							• Q cm ³ /min	29	18	8	5	36	29	10	6
							• V_e m/min	200	160	130	100	200	160	130	100
							• n min ⁻¹	1,270	1,020	830	640	1,220	980	800	610
VIII Cast-Iron GGG EN-JS10** EN-GJS-***							• f_z mm/t	2	2	1.5	1.5	2	2	1.5	1.5
							• V_f mm/min	10,190	8,150	4,970	3,820	12,240	9,790	5,970	4,590
							• a_p mm	1.5	1.2	1.1	0.9	1.5	1.5	1.0	0.75
							• a_e mm	35	35	35	35	37	37	37	37
							• Q cm ³ /min	535	342	183	120	679	543	215	127
							• V_e m/min	160	128	104	80	160	128	104	80
VI Stainless Steels High alloy Steels							• n min ⁻¹	1,020	810	660	510	980	780	640	490
							• f_z mm/t	1.5	1.5	1.2	1.2	1.5	1.5	1.2	1.2
							• V_f mm/min	6,110	4,890	3,180	2,440	7,350	5,880	3,820	2,940
							• a_p mm	1.5	1.2	1.1	0.9	1.5	1.5	1.0	0.75
							• a_e mm	35	35	35	35	37	37	37	37
							• Q cm ³ /min	321	205	117	77	408	326	138	82

IMPORTANTE:

- Questo utensile genera trucioli spessi e pesanti. Accertarsi una buona rimozione degli stessi per mezzo di aria, per evitare danni causati dal blocco dei trucioli. Il metodo raccomandato è l'adduzione interna dell'aria nel mandrino. (Porre maggior attenzione nel caso di lavorazioni in cavità con macchine ad asse verticale).
- Prima di eseguire lavorazione non presidiare, assicurarsi che la rimozione dei trucioli e le condizioni di taglio siano garantite in sicurezza.
- I trucioli possono causare tagli, scottature o danni agli occhi. Assicurarsi di installare una copertura di sicurezza intorno all'utensile e di indossare gli occhiali di sicurezza prima di eseguire la lavorazione.
- Sostituire l'inserto in tempo, allo scopo di evitare che una maggiore usura possa danneggiare il corpo fresa.

OBSERVACIONES

- Esta herramienta produce virutas gruesas y pesadas. Se debe asegurar la evacuación de la viruta para evitar roturas de placa. Se recomienda el soplado de aire a través del cabezal. (Se debe prestar especial atención a la evacuación de viruta al mecanizar cajas en centros verticales)
- Antes de dejar la máquina trabajando sola asegurarse de sacar las virutas y de utilizar condiciones de corte de seguridad.
- Las virutas pueden provocar cortes, quemaduras y heridas oculares. Asegurarse de tener instalada la protección de seguridad (puerta o similar.) mientras la herramienta trabaja y de llevar gafas durante las manipulaciones.
- Sustituir las placas de forma preventiva para evitar roturas por desgaste.

ASRF/M | Recommended Cutting Conditions

ISO50 / HSK100

D 63 (Z5) bore type				D 66 (Z5) bore type				D 80 (Z6) bore type				D 100 (Z8) bore type			
Q max	3D - 5D	5D - 7D	> 7D	Q max	3D - 5D	5D - 7D	> 7D	Q max	3D - 5D	5D - 7D	> 7D	Q max	3D - 5D	5D - 7D	> 7D
200	160	130	100	200	160	130	100	200	160	130	100	200	160	130	100
1,010	810	660	510	960	770	630	480	800	640	520	400	640	510	410	320
2	2	1.5	1.5	2	2	1.5	1.5	2	2	1.5	1.5	2	2	1.5	1.5
10,110	8,080	4,930	3,790	9,650	7,720	4,700	3,620	9,550	7,640	4,660	3,580	10,190	8,150	4,970	3,820
1.5	1.2	1.1	0.9	1.5	1.5	1.0	0.75	1.5	1.5	1.0	0.75	1.5	1.5	1.0	0.75
44	44	44	44	48	48	48	48	60	60	60	60	75	75	75	75
667	427	228	150	695	556	220	130	860	688	273	161	1,146	917	363	215
160	128	104	80	160	128	104	80	160	128	104	80	160	128	104	80
810	650	530	400	770	620	500	390	640	510	410	320	510	410	330	250
2	2	1.5	1.5	2	2	1.5	1.5	2	2	1.5	1.5	2	2	1.5	1.5
8,080	6,470	3,940	3,030	7,720	6,170	3,760	2,890	7,640	6,110	3,720	2,860	8,150	6,520	3,970	3,060
1.2	1.0	0.8	0.7	1.2	1.2	0.8	0.6	1.2	1.2	0.8	0.6	1.2	1.2	0.8	0.6
44	44	44	44	48	48	48	48	60	60	60	60	75	75	75	75
427	273	146	96	445	355	141	83	550	440	174	103	734	587	232	138
120	96	78	60	120	96	78	60	120	96	78	60	120	96	78	60
610	490	390	300	580	460	380	290	480	380	310	240	380	310	250	190
1.5	1.5	1.2	1.2	1.5	1.5	1.2	1.2	1.5	1.5	1.2	1.2	1.5	1.5	1.2	1.2
4,550	3,640	2,360	1,820	4,340	3,470	2,260	1,740	4,300	3,440	2,230	1,720	4,580	3,670	2,380	1,830
1	0.8	0.7	0.6	1	1	0.7	0.5	1	1	0.7	0.5	1	1	0.7	0.5
44	44	44	44	48	48	48	48	60	60	60	60	75	75	75	75
200	128	73	48	208	167	71	42	258	206	87	52	344	275	116	69
100	80	65	50	100	80	65	50	100	80	65	50	100	80	65	50
510	400	330	250	480	390	310	240	400	320	260	200	320	250	210	160
1	1	0.7	0.7	1	1	0.7	0.7	1	1	0.7	0.7	1	1	0.7	0.7
2,530	2,020	1,150	880	2,410	1,930	1,100	840	2,390	1,910	1,090	840	2,550	2,040	1,160	890
0.7	0.6	0.5	0.4	0.7	0.7	0.5	0.35	0.7	0.7	0.5	0.35	0.7	0.7	0.5	0.35
44	44	44	44	48	48	48	48	60	60	60	60	75	75	75	75
78	50	25	16	81	65	24	14	100	80	30	18	134	107	40	23
80	64	52	40	80	64	52	40	80	64	52	40	80	64	52	40
400	320	260	200	390	310	250	190	320	250	210	160	250	200	170	130
0.8	0.8	0.5	0.5	0.8	0.8	0.5	0.5	0.8	0.8	0.5	0.5	0.8	0.8	0.5	0.5
1,620	1,290	660	510	1,540	1,230	630	480	1,530	1,220	620	480	1,630	1,300	660	510
0.5	0.4	0.35	0.3	0.5	0.5	0.3	0.25	0.5	0.5	0.3	0.25	0.5	0.5	0.3	0.25
44	44	44	44	48	48	48	48	60	60	60	60	75	75	75	75
36	23	10	7	37	30	10	6	46	37	12	7	61	49	16	10
200	160	130	100	200	160	130	100	200	160	130	100	200	160	130	100
1,010	810	660	510	960	770	630	480	800	640	520	400	640	510	410	320
2	2	1.5	1.5	2	2	1.5	1.5	2	2	1.5	1.5	2	2	1.5	1.5
10,110	8,080	4,930	3,790	9,650	7,720	4,700	3,620	9,550	7,640	4,660	3,580	10,190	8,150	4,970	3,820
1.5	1.2	1.1	0.9	1.5	1.5	1.0	0.75	1.5	1.5	1.0	0.75	1.5	1.5	1.0	0.75
44	44	44	44	48	48	48	48	60	60	60	60	75	75	75	75
667	427	228	150	695	556	220	130	860	688	273	161	1,146	917	363	215
160	128	104	80	160	128	104	80	160	128	104	80	160	128	104	80
810	650	530	400	770	620	500	390	640	510	410	320	510	410	330	250
1.5	1.5	1.2	1.2	1.5	1.5	1.2	1.2	1.5	1.5	1.2	1.2	1.5	1.5	1.2	1.2
6,060	4,850	3,150	2,430	5,790	4,630	3,010	2,310	5,730	4,580	2,980	2,290	6,110	4,890	3,180	2,440
1.5	1.2	1.1	0.9	1.5	1.5	1.0	0.75	1.5	1.5	1.0	0.75	1.5	1.5	1.0	0.75
44	44	44	44	48	48	48	48	60	60	60	60	75	75	75	75
400	256	146	96	417	333	141	83	516	412	174	103	687	550	233	137
160	128	104	80	160	128	104	80	160	128	104	80	160	128	104	80
810	650	530	400	770	620	500	390	640	510	410	320	510	410	330	250
1.5	1.5	1.2	1.2	1.5	1.5	1.2	1.2	1.5	1.5	1.2	1.2	1.5	1.5	1.2	1.2
6,060	4,850	3,150	2,430	5,790	4,630	3,010	2,310	5,730	4,580	2,980	2,290	6,110	4,890	3,180	2,440
1.2	1.0	0.8	0.7	1.2	1.2	0.8	0.6	1.2	1.2	0.8	0.6	1.2	1.2	0.8	0.6
44	44	44	44	48	48	48	48	60	60	60	60	75	75	75	75
320	205	116	77	334	267	113	67	413	330	139	82	550	440	186	110

NOTES

- Utilisez de l'air pour évacuer les copeaux lourds et épais quand vous usinez avec cet outil. Le ré-usinage des copeaux peut endommager l'outil. La méthode recommandée est l'utilisation d'une broche avec refroidissement par le centre. (Accordez beaucoup d'attention à l'évacuation des copeaux avec les centres verticaux)
- Pour sauvegarder les conditions de coupe assurez vous de la bonne évacuation des copeaux avant de lancer l'usinage.
- Pour prévenir la cassa d'outil, il est important de remplacer les plaquettes dès l'apparition de signe d'usure.

NOTAS

- Assegure-se que usa ar na remoção das limas grossas e pesadas, produzidas quando se utiliza esta ferramenta. A obstrução de limas pode provocar a quebra da ferramenta. Recomenda-se o método de jato de ar no eixo-árvore. (Tomar especial cuidado na remoção de limas aquando do uso de centros de maquinação vertical).
- Para manter condições de corte seguras, certifique-se previamente da remoção eficiente das limas na maquinação sem operador.
- Para evitar quebra da ferramenta, é importante substituir as plaquetas ao primeiro sinal de desgaste.

➔ For more information about Modular Tools and available Shanks please check our brochures:

Indexable Modular No. 328.x



AS/ASC Shanks No. 708



⚠ Attention on Safety

1. Cautions regarding handling

- (1) When removing the tool from its case (packaging), be careful that the tool does not pop out or is dropped. Be particularly careful regarding contact with the tool flutes.
- (2) When handling tools with sharp cutting flutes, be careful not to touch the cutting flutes directly with your bare hands.

2. Cautions regarding mounting

- (1) Before use, check the outside appearance of the tool for scratches, cracks, etc. and that it is firmly mounted in the collet chuck, etc.
- (2) When preparing for use, be sure that the inserts are firmly mounted in place and that they are firmly mounted on the arbor, etc.
- (3) If abnormal chattering, etc. occurs during use, stop the machine immediately and remove the cause of the chattering.

3. Cautions during use

- (1) Before use, confirm the dimensions and direction of rotation of the tool and milling work material.
- (2) The numerical values in the standard cutting conditions table should be used as criteria when starting new work. The cutting conditions should be adjusted as appropriate when the cutting depth is large, the rigidity of the machine being used is low, or according to the conditions of the work material.
- (3) Cutting tools are made of a hard material. During use, they may break and fly off. In addition, cutting chips may also fly off. Since there is a danger of injury to workers, fire, or eye damage from such flying pieces, a safety cover should be attached when work is performed and safety equipment such as safety goggles should be worn to create a safe environment for work.
- (4) There is a risk of fire or inflammation due to sparks, heat due to breakage, and cutting chips. Do not use where there is a risk of fire or explosion. Please caution of fire while using oil base coolant, fire prevention is necessary.
- (5) Do not use the tool for any purpose other than that for which it is intended.

4. Cautions regarding regrinding

- (1) If regrinding is not performed at the proper time, there is a risk of the tool breaking. Replace the tool with one in good condition, or perform regrinding.
- (2) Grinding dust will be created when regrinding a tool. When regrinding, be sure to attach a safety cover over the work area and wear safety clothes such as safety goggles, etc.
- (3) This product contains the specified chemical substance cobalt and its inorganic compounds. When performing regrinding or similar processing, be sure to handle the processing in accordance with the local laws and regulations regarding prevention of hazards due to specified chemical substances.

“MOLDINO” is a registered trademark of MOLDINO Tool Engineering, Ltd. in Japan.

Specifications for the products listed in this catalog are subject to change without notice due to replacement or modification.

Always up to date: Please check our P50 QuickFinder

P50 F PRODUCTION50®
QuickFinder www.moldino.eu/quickfinder

MOLDINO Tool Engineering Europe GmbH

Itterpark 12 · 40724 Hilden · Germany · Phone +49 (0) 21 03-24 82-0 · Fax +49 (0) 21 03-24 82-30

E-Mail info@moldino.eu · Internet www.moldino.eu

© 2020 by MOLDINO Tool Engineering Europe GmbH · 4th Edition · Printed in Germany